

# End of Cut Tuning (reducing gouge)

---



There are several reasons you may see a gouge at the end of a cut.


## The Cause

Gouging typically occurs when:

- The torch returns to the a location already cut—typically the start location—and does not shut off
- The torch returns to a location already cut and has been instructed to shut off (and does), but there is still a pool of liquefied metal around the torch, and the remaining (or ongoing) air pressure in the torch nozzle blows out the additional metal

This issue usually occurs on cuts where the part is between the torch and the ground, which means the first cut on a part and all holes. It does not typically occur on the last cut where the part falls off because the torch is grounding into the remaining pipe (and thus arcing that direction).


However, depending on the tuning issue, gouging can occur on both ends.



## Solutions Overview


### Use Leadout

Instruct the machine to perform a Leadout before the torch reaches the end of the part. This picture is showing a Leadout that is probably a little too early. Tuning this will be covered farther down.



### Turn Torch Off Early


Instruct the machine to turn off before it gets to the end of the cut. This accounts for not only how long it takes to turn the torch off, but also how long it takes for the torch to stop blowing liquefied metal off the part.



### Use both Leadout and Turn the torch off early

This can be useful as you want the torch to move away, but if you can turn the torch off and have it moving away, only blowing liquefied metal, but not arcing (and reaching toward the part, and creating more liquefied metal) then that can produce an even better result.

Here is what that looks like in PyperServer. (Again the Leadout for this is probably too far back.)



## Parameters to adjust in PypeServer

Note that because of the dynamic nature of plasma cutting, operators may need to adjust these for differing conditions. See [Factors That Affect Gouging](#).

### Leadout

Check this to include a Leadout when the cut is using a Leadin.

### Leadout Start Distance

This is the distance back from the end of the cut where the Leadout will begin its arc off the part. The arc radius is automatically calculated and is typically about the Kerf diameter.

### Early Off Distance

Provides a fixed distance from the end of the cut at which the torch will be signaled to turn off.

### Torch off lag time

Torch off lag time is used to calculate a distance based on the given Feedrate.

System Settings				
List Management	Server Connections	Default Cut Values	Machine Settings	Sys
Admin logout...	Firmware Revision		7.021	
	Machine Name		M1	M2
	Min Pipe OD		1.500	1.500
	Max Pipe OD		100.000	100.000
	Max Pipe Length		400.000	500.000
	Cutter Dead Zone		8.000	8.000
	Max Feed Rate		1000.000	1000.000
	Com Port		COM6	COM6
	Chuck Stop Dist From Machine Zero		-2	0
Torch Name		Etch On W...	Plasma on ...	Gas on W3...
Cutter Beam Divergence Ang		0	0	0
Kerf		0.010	0.10	0.125
Pierce Angle		0.00	10.00	10.00
Leadin		0.250	0.250	0.250
Leadout		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Leadout Start Distance		0.100	0.15	0.000
Early Off Dist		0.000	0.30	0.000
Torch off lag time (msec)		0	0	100
Tab Length				
Max Bevel Angle U		72.00	40.00	80.00
Max Bevel Angle V		71.00	40.00	80.00
Admin Configs				

## Using Leadout and Leadout Start Distance

This is by far the easiest and most consistent solution to not gouging parts. Used alone it will leave a small ridge where the start and end cut were exiting the cut line.

Here are a couple examples of a well-tuned Leadin and Leadout.



Try starting with a **Leadout Start Distance** that is about 2X Kerf Diameter and go from there.

You can try to get the Leadin and Leadout even closer, but the plasma arc will likely begin to reach somewhere into the part as the end-of-cut torch beam enters into the start-of-cut gap.

## Calculating Early Off Distance

Early Off Distance defines a fixed distance the torch will be signaled to turn off before the end of the cut.



NOTE: This distance is independent of the Leadout Start Distance, meaning that the torch will turn off the distance from the actual end of the cut (not factoring in the Leadout path location or distance).

Here is one way to calculate an early off distance.

1. Turn off Leadout. Leadin is good because measuring a pierce hole is difficult.
2. Set the Early Off Distance to one inch,
3. Cut a straight cut around the pipe
4. Measure the distance not cut between the start of the cut and then end of the cut. You'll need to guess a little because of the Leadin arc. The closest edge of the leadin will be most accurate.
5. Set the Early Off Distance as  $1'' + (0.75 * \text{Kerf}) - \text{the measured distance}$

The math:

With numbers:  $(1 + (0.75 * .1)) - 0.6 = .475$



## Torch off lag time

Torch off lag time calculates an early off distance by  $\text{Lag Time} * \text{Feedrate}$ . The higher the feed rate, the longer the early off distance.

For example, a lag time of one second (1000 milliseconds entered in PyeServer), and a feed rate of 60 inches per minute, would result in an early off distance of one inch.

$(60 \text{ inches per minute} / 60 \text{ seconds} = 1'' / \text{second}, \text{ so a } 1 \text{ second lag time} = 1 \text{ inch.})$

Torch Off Lag Time can be useful where you have cuts with different Feedrates (like end-cuts and holes), and your primary issue is the pressurized air lag time (continued blow of liquefied metal). The Torch off distance will adjust between faster and slower cuts.

### Note:

At higher Feedrates, the size/length of the liquefied metal can be a limiting factor on this lag-time method. The pool of metal may not extend as far as the calculated lag time. In such cases, it is likely better to use early off distance.

## Using Both Parameters


When using both early torch-off timing parameters, the system will take the greater of the two off distances. It will not sum the two.

You can see the torch off distances (if long enough) on cuts as gray (torch off) markers. (You may not always see these, as the markers on screen are a subset of the actual steps sent to the machine.)


Example:

**Early Off Dist = .5, Torch Off Lag Time = 750 (milliseconds)**

Feed Rate = 20: torch off dist = .5



Feed Rate = 60: torch off dist = .750



## Factors that affect gouging

How long a torch blows liquefied metal off the part is governed by a number of parameters.

- Air pressure and air volume between air valve and torch
  - Affects how long the torch will blow.
- Time it takes for the air valve to actually close.
  - Seems to vary from torch to torch. Maybe how the solenoid is designed?
- Feed rate
  - How fast you are travelling through the liquefied pool of metal is huge.
- Deteriorating or changing to different consumables
- Change in feed gas
- Amperage and Ground quality
  - how much metal are you liquefying around the torch
  - how much reach your torch will have
- Pipe thickness, Pipe size/mass and number of local cuts made to pipe
  - Affects how hot the pipe gets, which changes how much metal liquifies around the torch
- Kerf and plasma beam shape
  - Affects heat and liquefied metal pool size
- The time it takes for the torch to turn off
  - Varies from torch to torch, but I don't think I've seen a significant difference.

As these factors change (very dynamically), so will gouging. **Because these parameters often vary, You may need to change the end cut tuning parameters with different cutting situations.**

**Example of different feed rates** (back side of the cuts)  
Different feedrates with all other settings the same. Note that results might notably vary if the cuts were slow to fast or fast to slow, as the metal would significantly change temperature with successive cuts.

